



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D135-692-041
Job Sheet 187518



006907

Part No: D135-692-041

Job Qty: 1 ea

Part Name: EC135 Bearpaw Wearplates



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 12/6/18

Job Tracking No:

Due Date: 12/24/18

Created By: Marie Lajeunesse

Type: SOLD

Description:

Note: DWG DSI9400 REV A, DSI9750 REV A IPP Rev:A new issue ECN1089 08-02-04 DD verified by:EC IPP
Rev:B ECN 1132 08-02-20 DD verified by:EC

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
90	Start up Operation	1 Ea	12/24/18	12/24/18	0.00	0.00	Start Up Stores/Pkg-1		DEC 06 2018
110	Packaging	1 pcs	12/24/18	12/24/18	0.00	0.00	Packaging1-1		DEC 27 2018
120	QC	1 pcs	12/24/18	12/24/18	0.00	0.00	QC4		DEC 27 2018
130	Packaging	1 pcs	12/24/18	12/24/18	0.00	0.00	Packaging3-1		DEC 27 2018
135	DC	1 pcs	12/24/18	12/24/18	0.00	0.00	DC		DEC 27 2018
140	QC21-FG	1 Ea	12/24/18	12/24/18	0.00	0.00	QC21		DEC 27 2018

Part Op 130 - Identify and pack for shipping as per PPP D135-692-041 CHG001 PPP Rev: C
Descriptions: 135 - Photocopy bluefile and create labels per PPP D135-692-041 CHG002

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
AN4-11A	Bolt	4 Ea (4 ea)	90-Start up Operation	5117002
AN4-13A	Bolt	8 Ea (8 ea)	90-Start up Operation	5115326
D2529	Washer	8 pcs (8 ea)	90-Start up Operation	5033981
D3719-041	Wearplate Assembly	2 Ea (2 ea)	90-Start up Operation	5135815
MS21042L4	Nut	12 Ea (12 ea)	90-Start up Operation	50109236
NAS1149D0463J	Washer	8 Ea (8 ea)	90-Start up Operation	5092780

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
90-Start up Operation	AN4-11A	4	154	0
	AN4-13A	8	758	0
	D2529	8	872	0
	D3719-041	2	1	0
	MS21042L4	12	2,906	0
	NAS1149D0463J	8	3,911	0

Part Specifications

Specifications could not be found.

Entered: _____ Date: _____



WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only ☐

Job: _____ Part No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐	DEPARTMENT/PROCESS <table style="width: 100%;"> <tr> <td>Skid-tube ☐</td> <td>Cross tube ☐</td> <td>Eng. (Non-AW) ☐</td> <td>Engineering ☐</td> </tr> <tr> <td>Machining ☐</td> <td>Small Fab ☐</td> <td>Prod. Eng. Coord. ☐</td> <td>Water Jet ☐</td> </tr> <tr> <td>Large Fab ☐</td> <td>Finishing ☐</td> <td>Rec/Store/Packaging ☐</td> <td>Supplier Quality ☐</td> </tr> </table>	Skid-tube ☐	Cross tube ☐	Eng. (Non-AW) ☐	Engineering ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Water Jet ☐	Large Fab ☐	Finishing ☐	Rec/Store/Packaging ☐	Supplier Quality ☐
Skid-tube ☐	Cross tube ☐	Eng. (Non-AW) ☐	Engineering ☐											
Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Water Jet ☐											
Large Fab ☐	Finishing ☐	Rec/Store/Packaging ☐	Supplier Quality ☐											

Date :	Sequence #:	QTY Affected :	MRB (QSI042)
--------	-------------	----------------	--------------


Work Order Deviation 	Disposition 	Completed By
		Lead hand / Supervisor
		QC / QA Coordinator

FAULT CATEGORY			
☐ Pressure/Forced ☐ Bending ☐ Crushing ☐ Cracks ☐ Crimp/Kink/Ripple/Wave/Twist ☐ Marks/Chatter ☐ Mislabeled	☐ Contamination ☐ Misaligned/off center ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Incomplete/Unclear Instructions ☐ Drill Holes ☐ Fit/Function	☐ Power Loss/Surge ☐ Folio/Program ☐ Grain Direction ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set/Set-up	☐ Positioned Wrong ☐ Outside Tolerance ☐ Drawing ☐ Finish ☐ Part Lost/Missing ☐ Misread

Other/Details:

Material	☐
Product Improvement	☐
Process Improvement	☐
Human Factors	☐

Dart Aerospace Ltd.
1270 Aberdeen Street
Hawthorn, ON M6A 1K7
CANADA
TEL: 1 613 632-5200
Email: sales@dartaero.com
www.dartaerospace.com



Container No: S137353



Part: D135-692-041

Job No: 187518

Serial No/Batch: S137353

Revision: _____
 Inspector: _____
 Exp Date: _____
 Instructions: FAA STC SRD1042SE 17096/22/18a LoA 120S -

3.0 PARTS LIST

The DSI 9750-011 Clamp Relocation Kit can be procured from Dart to install D135-692-041 on D135-692-011 at CHG 002 and earlier, and includes hardware for Qty 2x skid tubes.

Qty -011	Part Number	Description
X	DSI 9750-011	Clamp Relocation Kit
8	D2529	WASHER
4	AN4-11A	BOLT
4	MS21042L4	NUT

The parts list for IIN-D135-692 and ICA-D135-692 is amended as follows:

Qty -011	Qty -041	Part Number	Description
X		D135-692-011	BEARPAW INSTALLATION
	X	D135-692-041	WEARPLATE KIT
4		D2182B060	RUBBER CUSHION
8		D2274	RADIUS BLOCK
2		D3049-1	BEARPAW
8	8	D2529	WASHER
4		D2519	CLAMP
	2	D3719-041	WEARPLATE
	4	AN4-11A	BOLT
8	8	AN4-13A	BOLT
8	12	MS21042L4	NUT (OR MS21042-4)
8	8	NAS1149D0463J	WASHER
4		QS100M24S	CLAMP

4.0 WEIGHT AND BALANCE

There is a negligible weight and balance change associated with this modification.

DESIGN	ML	DART AEROSPACE USA, INC. EUGENE, OR	
DRAWN	ML		
CHECKED	<i>JP</i>	DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9750	SHEET 2 OF 5
APPROVED	<i>[Signature]</i>	TITLE	SCALE
DE APPR.	<i>[Signature]</i>	INSTALL MODIFICATION	NTS
DATE	16.06.01	COPYRIGHT © 2016 BY DART AEROSPACE USA, INC. THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.	

Change Record

PAGE 1 OF 1

Part Number: D135-692-041

Description: BEARPAW WEARPLATE INSTALLATION

[illegible]

